

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

			and the last of the same of th	the state of the s	
This section must be o	completed in its entirety t	to constitute a vali	d maintenance p	ermit. This permit n	nust be completed
	ning maintenance activiti				ice activity.
Date of Maintenance:	10/27/16 Reason	for Maintenance:	ROUTINE		
Property Address: /5	991 Uppor 3	34th ST. S. Pr	operty Owner's N	Name: MATT SN	ELLING
Municipality: AF		Property Iden			
	: <u>K4745 K4757</u> N				15
Maintenance Fermit No	<u>K771311131</u> "	idiredired Harris and			
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
X Tank(s) Pumped ☐ Sludge and scum measured		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b		Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greate					if 25% or greater
 Were all covers securely replaced? Yes \(\sum \text{No} \) Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
	Tank	Leaking Out	Leaking In	Cover Damage	ş.
	Septic/Holding Tank #1	☐ Yes 风No	☐ Yes ②No	☐ Yes 🗷 No	
	Septic/Holding Tank #2	☐ Yes ☑No	☐ Yes 🔼 No	☐ Yes 🗹 No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	•:
4. How many gallons	of septage were removed	1?			
Tank #1 1 (36) gal Tank #2 1/900 gal Pretreatment tank gal Pump Tank gal					
5. Other information	: List any troubleshooting	g, minor repairs co	nducted, tank sa	fety concerns, or oth	er concerns.
menhok	Covers		Δ		
6. Location of septage disposal: WTP St Paul					