

6.

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section mu	ist be completed in its ent	irety to constitute	a valid maintenand	e permit. This per	mit must be complete
prior to p	performing maintenance a	ctivities and remain	on-site for the du	ration of the maint	enance activity
Date of Maintena	nnce: $\frac{1}{3}$	eason for Maintenance	Nag.		and addition.
Property Address	: 1043A · 530th	St. no.	Property Owner'	s Name: Josef	Peterson
Municipality:	zandia ZIP:	55073 Property I	dentification Numb	per:	
Maintenance Pern	nit No:	Maintainer Name	and License No.	OST-#2	No
		4000	ed how a sign of the s		chine grange the
Tank(s) Pumpe	ed	Liquid Level o	f Tank i	n	
☐ Sludge and scu	m measured	Sludge Level i	n Tank i	n Scum Level in Tar	ıkin
Do tanks need	to be pumped?	Sludge + Scum	/ Liquid	Level X 10	00
☐ Yes ☐ No	(if no provide measurement			anks must be pumpe	
3. Is there evidence	securely replaced?	septic, holding, pret	reatment or pump ntenance hole cov	tank below the opeers?	erating depth or
*	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☒No	
×	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
		42			
4. How many gallon	s of septage were remove	u:			
	s of septage were removed gal Tank #2	gal Pretreatment	tank ga	l Pump Tank	gal
Tank #1 1250	20 2000 M	gal Pretreatment	0	Pump Tank y concerns, or other	gal r concerns.
Tank #1 1250	gal Tank #2	gal Pretreatment	0		