12-9



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must l	be completed in its entiret	y to constitute a v	alid maintenance	permit. This permit	must be completed	
prior to per	forming maintenance activ	ities and remain o	n-site for the dura	tion of the maintena	nce activity	
Date of Maintenance	e: <u>1-23-17</u> Reaso	n for Maintenance:	Routin.			
Property Address:	6595 4th St	N	Property Owner's I	Name: Karen	Danilaiti	
Municipality:			entification Numbe			
	No: 14230C2782				ewer Service/L1673	
Mainter	nance Performed	Tank Mea	surement (must be	e completed if tanks I	NOT pumped)	
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to	o be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)			= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	emove septage: Maintena					
	ecurely replaced? Yes		and and and and and and			
3. Is there evidence	e of tank leakage from a sen naged, cracked, or structur	ptic, holding, pret	reatment or pump ntenance hole cove	tank below the opera ers?	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🗖 No	☐ Yes ♠ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	s of septage were removed	?				
Tank #1 1250	The second secon		t tankg	al Pump Tank	gal	
5. Other information	n: List any troubleshooting	- , minor repairs co	nducted, tank safe	ty concerns or other	Concorns	
			and the same	ty concerns, or other	concerns.	
			<u> </u>			
6. Location of septag	e disposal:			114		