

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a v	alid maintonanco	normit This		
<u>prior</u> to performing maintenance activi	ties and remain o	n-site for the dur-	permit. This permit	must be completed	
Date of Maintenance: 12-8-16 Reason	for Maintenance:	Routine			
Property Address: <u>895 Mwk Ave</u> Ct.	N.	Property Owner's	Name: Gene T)ertelli	
Municipality: ZIP:					
Maintenance Permit No: 60539 m.533				ewer Service/L1673	
Maintenance Performed	Tank Mea	surement (must be	e completed if tanks	NOT pumped)	
Tank(s) Pumped	Liquid Level of	Tank in			
☐ Sludge and scum measured	The second secon	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
 Access used to remove septage: Maintena Were all covers securely replaced? Yes Is there evidence of tank leakage from a sepevidence of damaged, cracked, or structure. 	□ No	reatment or nump	tank holow the area	rating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?					
Tank #1 7250 gal Tank #2 /250	gal Pretreatmen	t tank ga	al Pump Tank	gal	
5. Other information: List any troubleshooting, manhote under landscaping	minor repairs co	nducted, tank safe	ty concerns, or othe	r concerns.	
6. Location of septage disposal:			1		