

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section mu	st be completed in its enti	irety to constitute	a valid maintenand	ce permit. This permi	t must be complete	
prior to p	erforming maintenance ac	ctivities and remain	on-site for the du	ration of the mainten	ance activity.	
Date of Maintena	nce: 3-16-17 Re	ason for Maintenanc	$e: \underline{P_i M_i}$			
Property Address:	23975 Heath	Avenue 1	Property Owner	's Name: Dorothy S	tainbrook	
Municipality:	ZIP:		dentification Numb			
Maintenance Perm	nit No: X 533, 5500	Maintainer Name	and License No.	DSST - #21	6	
Same	२ (स्थे) १ ६ (स्थे स्टॉन्स्ट्रेन्स्ट्रेन्स्ट्रेन्		eding a serior of the serior		Cost (Logicality)	
Tank(s) Pumpe	d	Liquid Level o	f Tanki	n		
☐ Sludge and scur		Sludge Level i	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need	Section 1981	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No	(if no provide measuremen			anks must be pumped		
1. Access used to r	emove septage: Mainte	nance Hole Other	(enter authorization	code)		
2. Were all covers	securely replaced? V	s 🗆 No				
Is there evidence evidence of dark	e of tank leakage from a s maged, cracked, or structi	eptic, holding, preturally unsound mai	treatment or pump ntenance hole cov	tank below the opera ers?	ating depth or	
9	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☑No	☐ Yes ⊠No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☑No	☐ Yes ☐#fo	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1 1300	gal Tank #2	gal Pretreatment	tank ga	l Pump Tank	gal	
. Other information	: List any troubleshooting					
Location of costs	dia					
. Location of septage	disposat:					