

# OSTP Soil Observation Log

Project ID:



Client/ Address:	7707 St. Croix Trail S	Legal Description/ GPS:	10.027.20.31.0003
------------------	------------------------	-------------------------	-------------------

Soil parent material(s): (Check all that apply)     Outwash     Lacustrine     Loess     Till     Alluvium     Bedrock     Organic Matter

Landscape Position: (check one)     Summit     Shoulder     Back/Side Slope     Foot Slope     Toe Slope    Slope shape: \_\_\_\_\_    CC

Vegetation	Lawn	Soil survey map units	298B-Richwood Silt Loam, 2-6%	Slope%	2.0	Elevation:	878
------------	------	-----------------------	-------------------------------	--------	-----	------------	-----

Weather Conditions/Time of Day: \_\_\_\_\_ PM/Raining \_\_\_\_\_ Date: 04/25/17

Observation #/Location: \_\_\_\_\_ County Verification Observation \_\_\_\_\_ Observation Type:  Auger     Probe     Pit

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	I----- Structure-----I		
							Shape	Grade	Consistence
0-24"	Silt Loam		10YR3/2				Blocky	Moderate	Friable
24-39"	Clay Loam		10YR4/4				Blocky	Moderate	Firm
39"	Bedrock	>50%					Massive		

Comments: 44°50'15.8528" 92°47'44.7724"

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

<b>Chris LeClair</b>		<b>C6836</b>	<b>4/25/2017</b>
(County Inspector)	(Signature)	(License #)	(Date)