



## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

# Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	rety to constitute	a valid maintenance	e permit. This perm	nit must be complete	
<u>prior</u> to performing maintenance ac	tivities and remain	on-site for the du	ration of the mainte	nance activity.	
Date of Maintenance: 4-19-17 Rea					
Property Address: 2090 Mendel	Aven	Property Owner's	s Name: Ron 1	H; elle	
Municipality: Lak Elmo ZIP: 5					
Maintenance Permit No: <u>b8 536K 5512</u>				116	
South the property of the property of the		ek her nêmî newî			
☑ Tank(s) Pumped	Liquid Level o	f Tank i	n		
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?	Sludge + Scum	/ Liquid	Level X 10	0 ,	
☐ Yes ☐ No (if no provide measurement	s) = % Sludge & S	cum Ta	anks must be pumped	d if 25% or greater	
2. Were all covers securely replaced?   3. Is there evidence of tank leakage from a secure evidence of damaged, cracked, or structum.	eptic, holding, pre	treatment or pump ntenance hole cove	tank below the opeers?	rating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ♥No	☐ Yes ☑ No	☐ Yes ☑No		
Septic/Holding Tank #2	☐ Yes ☑ No	☐ Yes ☑No	☐ Yes ☑No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
How many gallons of septage were removed	1?				
Tank#1/500 gal Tank#2/000	gal Pretreatment	tankga	l Pump Tank	gal	
Other information: List any troubleshooting				concerns.	
Location of septage disposal:					



# Washington County

6.

#### DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

# Subsurface Sewage Treatment System Maintenance Permit

This section must I	be completed in its enti	irety to constitute	valid maintenance	e permit. This perm	nit must be complete
<u>prior</u> to peri	forming maintenance ac	ctivities and remain	on-site for the du	ration of the mainte	enance activity.
Date of Maintenance	: 4-19-17 Re	ason for Maintenanc	e:		
Property Address:	13233 Nothb	WOOK AVEN	Property Owner's	Name: Fred	O Neil
Municipality: 57	Mwater ZIP: 5	5082 Property I	dentification Numb	er:	
	No: V4136m5513				110
A Garage	મું મુક્ત માટે કહી ભાગાનું છું. શહેર કેન્દ્ર મુક્ત માટે કહી સામાનું મુખ્ય સ્થાપન કેન્દ્ર		· Empoporation	or the lates of the	er. Burkingbell
Tank(s) Pumped		Liquid Level o	f Tank ir	1	
Sludge and scum r	neasured	Sludge Level i	n Tank ir	Scum Level in Tan	k in
Do tanks need to be pumped?   Sludge + Scum / Liquid Level X 100					, 00
☐ Yes ☐ No (if	no provide measuremen	ts)    = % Sludge & S	cum Ta	anks must be pumpe	d if 25% or greater
14.	nove septage: Amainte				<i>,</i>
. Were all covers see	curely replaced? Ye	s 🗆 No			7
. Is there evidence of evidence of dama	of tank leakage from a s ged, cracked, or struct	eptic, holding, preturally unsound main	reatment or pump ntenance hole cove	tank below the opers?	erating depth or
e.	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yeso BiNo	☐ Yes ⊠No	☐ Yes ⊠No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Í	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
How many gallons of	septage were removed	d?			
Tank #1 1400	gal Tank #2	gal Pretreatment	tank ga	l Pump Tank	gal
	ist any troubleshooting				r concerns.
ocation of septage di	sposal:				



## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

7	This section must be co	mpleted in its enti	irety to constitute	a valid maintenance	e permit. This perm	nit must be comp			
	This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be comp prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.								
	Date of Maintenance: 4-20-17 Reason for Maintenance:								
	roperty Address: ///2					Mc Caithy			
M	unicipality: Mar.	ve ZIP: C	5047 Property	dentification Numb	er:	,			
	aintenance Permit No: v					110			
	(Filtress)			建原金原金矿 机燃料		er ja jagariti			
X	Tank(s) Pumped		311	f Tank i					
	Sludge and scum measu	red	Sludge Level i	n Tank i	Scum Level in Tan	k in			
	Do tanks need to be pu	mped?			Level X 10				
	☐ Yes ☐ No (if no pro	ovide measurement	ts) = % Sludge & S	cum T	anks must be pumped	d if 25% or greater			
1. /	Access used to remove :	eptage: AMainte	nance Hole  Other	(enter authorization	code)	<i>3</i>			
2. V	Vere all covers securely	replaced? X Ye	s 🗆 No		***************************************	*			
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?									
		Tank	Leaking Out	Leaking In	Cover Damage				
	Septic	/Holding Tank #1	☐ Yes 🖾 No	☐ Yes ⊠No	☐ Yes ⊠No				
-	Septic,	Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No				
	Pretre	atment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No				
	Pump 1	ank .	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No				
4. Ho	w many gallons of sept	age were removed	1?						
Ta	ank#1 1275 gal	Tank #2	gal Pretreatment	tank ga	Pump Tank	gal			
5. Otl	ner information: List an	y troubleshooting							
6 100	ation of septage disposa								
v. LUC	arioi or achrake nishora								