DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Per

Subsurface Sewage Treatment System Maintenance Permit

			d interance nor	mit This parmit mu	st be completed
This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 11-09-16 Reason for Maintenance: Koutine Maintenance					
Property Address: 15100 Square a Ke Trl N Property Owner's Name: Mark Diessner					
Municipality: Stillwater ZIP:55082 Property Identification Number:					
Maintenance Permit No	: 14 to 237d 3303 Ma	aintainer Name and	d License No. Ron's	Sewer Service/ L2103	3
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: A Maintenan	ce Hole 🗌 Other (e	nter authorization co	de)	
2. Were all covers securely replaced? Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes TNo	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 1500	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information	: List any troubleshooting,	, minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.
	<i>y</i>				
6. Location of septage disposal:					
				RECEIVE	ED
					CONTRACTOR OF THE PARTY OF THE

NOV 16 2016

PUBLIC HEALTH