

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety to				
prior to perform	ning maintenance activitie	es and remain on-	site for the duratio	n of the maintenanc	e activity.
	11-11-16 Reason f			Mainte	nance
Property Address:	100 Leeward	ANC.S. PI	operty Owner's Na	me:Brandor	Herdt
			tification Number:		_
Maintenance Permit No	::W8017V3318 M	aintainer Name an	d License No. Ron's	Sewer Service/ L210	3
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	curely replaced? Yes [of tank leakage from a sepinged, cracked, or structura	tic, holding, pretr	eatment or pump t tenance hole cover	cank below the opera rs?	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes 🎢 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	of septage were removed	?			
Tank #1 1500	of septage were removed gal Tank #2	? gal Pretreatmen	t tankg	al Pump Tank	gal
Tank #1 1500		? gal Pretreatmen	t tankg	al Pump Tank	gal r concerns.
Tank #1 1500	of septage were removed gal Tank #2	? gal Pretreatmen	t tankg	al Pump Tank	gal r concerns.
Tank #1 1500	of septage were removed gal Tank #2 : List any troubleshooting	? gal Pretreatmen	t tankg	al Pump Tank	gal r concerns.