



## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 12-19-16 Reason for Maintenance: Routine Maintenance					
Property Address: 15255 814 57 11 Property Owner's Name: Dang Jack Je					
Municipality: Lakeland ZIP: Property Identification Number:					
Maintenance Permit No: 1636 m 4077 Maintainer Name and License No. Ron's Sewer Service/ L2103					
Maintenance Permit No	: r1656m 407) M	aintainer Name an	a License No. Ron's	Sewel Service/ E210	J
Maintenar	ice Performed	Tank Meas	urement (must be o	completed if tanks N	OT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?   Sludge + Scum / Liquid Level X 100					*
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater					
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced? Yes \sum No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ♠ No	☐ Yes ♣ No	☐ Yes ∰No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 /250	gal Tank #2	gal Pretreatmen	tankga	l Pump Tank	gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
1 <u></u>					
6. Location of septage	e disposal:				