

Subsurface Sewage Treatment System Maintenance Permit

				AND RESIDENCE OF THE PARTY OF T		
This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.						
Date of Maintenance: 1-18-17 Reason for Maintenance: Routine Maintenance						
Property Address: 8719 Gakgree Are 5 Property Owner's Name: Charles Grote						
Municipality: Hastings ZIP: 55033 Property Identification Number:						
Maintenance Permit No	15804011504085 N	Maintainer Name an	d License No. Ron's	S Sewer Service/ LZ10.	3	
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)	
		Liquid Level of Tank in				
Tank(s) Pumped			Sludge Level in Tank in Scum Level in Tank in			
Sludge and scum m			Sludge + Scum / Liquid Level X 100			
Do tanks need to b						
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater						
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)						
2. Were all covers securely replaced? Yes No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes TNo	☐ Yes TNo		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	d?				
Tank #1 1250 gal Tank #2 gal Pretreatment tank gal Pump Tank gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
-						
6. Location of septage disposal: MCFC						