Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety	to constitute a vali	d maintenance pe	rmit. This permit mu	st be completed
prior to perform	ning maintenance activiti	es and remain on-	site for the durati	on of the maintenance	e activity.
Date of Maintenance:	$3-27-17_{\text{Reason}}$	for Mainţenance: _	Res /	lain T	
21	150 011	1 1 /	our auto Ou un auto Na	ma Warno	Schmitt
Property Address: <u>C</u>	USQ Ulinda	IN /V P	operty Owner's Na	ame: Wayne	20111111
Municipality:	india ZIP: 550	Property Iden	tification Number:		_
Maintenance Permit No	:0010966131 N	Naintainer Name an	d License No. Smil	ie's Sewer Service/L24	128
Maintenance Fernite No		- Tame and			
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: Maintena	nce Hole 🗌 Other (e	nter authorization co	ode)	
2. Were all covers sec	curely replaced? Yes	□ No			
3. Is there evidence of	of tank leakage from a sep ged, cracked, or structur	tic, holding, pretr	eatment or pump tenance hole cove	tank below the opera rs?	ting depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐No	☐ Yes ☑No	☐ Yes ①No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	1?			
Tank #1 1250 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal					
5. Other information	: List any troubleshooting	— g, minor repairs co	nducted, tank safe	ety concerns, or other	r concerns.
	11				
6. Location of septage	e disposal:	2/10			