

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	, to constitute a va	lid maintenance pe	ermit. This permit m	iust be completed	
<u>prior</u> to perfo	rming maintenance activi	ties and remain on	-site for the durati	on of the maintenan	ce activity.	
Date of Maintenance:	6/27/16 Reason	n for Maintenance:	Routino) .		
Date of Maintenance.	21100	Ω so	7(0-20-20-7-20-7-20-7-20-7-20-7-20-7-20-	2.15	6001 +	
Property Address: 2	34 St Chory	11/0.7/. F	roperty Owner's N	ame: ([kkstta)	Egifleston	
Municipality:	reland IP: 55	5043Property Ide	ntification Number:			
	lo: 18918 v 1570				5	
	1011011370					
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks h	(OT pumped)	
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in ⁻	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if) = % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater				
4.4		U-I M OV (40 1 0	P	
	nove septage: Mainten	1	enter authorization co	D (255 po	√	
	curely replaced? 🛭 Yes					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🏿 No		200		
		Li res 🖎 No	☐ Yes ☐ No	Yes No		
	Septic/Holding Tank #2	☐ Yes ☑ No	☐ Yes 🖺 No	☐ Yes No☐ Yes No		
	Septic/Holding Tank #2 Pretreatment Tank	100		Serial Vol. Serial Seri		
		☐ Yes M No	☐ Yes 🔊 No	☐ Yes No.		
4. How many gallons	Pretreatment Tank	☐ Yes ☑ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
£ 157	Pretreatment Tank Pump Tank of septage were remove	☐ Yes M No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No☐ Yes ☐ No☐	gal	
Tank #1 1,000	Pretreatment Tank Pump Tank of septage were remove	☐ Yes MNo ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ gal Pretreatmen	 ☐ Yes	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ All Pump Tank		
Tank #1 1,000	Pretreatment Tank Pump Tank of septage were removed gal Tank #2 : List any troubleshooting	☐ Yes MNo ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ gal Pretreatmen	 ☐ Yes	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ All Pump Tank		
Tank #1 1,000	Pretreatment Tank Pump Tank of septage were removed gal Tank #2 : List any troubleshooting	Yes Mo Yes No Yes No Yes No d? gal Pretreatmen g, minor repairs co	Yes No Yes No Yes No t tank g	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ All Pump Tank		