

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety to				
	ming maintenance activitie		~	on of the maintena	nce activity.
	12-22-16 Reason f				
Property Address:	9195 Janaca	Are P	roperty Owner's Na	me: Long Ma	ica
Municipality: Skill	Jover zip: 5508	2 Property Ider	tification Number:		
	: M7751M5620 M				lonks-serv
Maintenan	ce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers sec3. Is there evidence o	ove septage: Amaintenan curely replaced? Yes C of tank leakage from a sept ged, cracked, or structura	☐ No tic, holding, pretr	eatment or pump	tank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ⊠No	☐ Yes 🏹 No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	•
4. How many gallons	of septage were removed?				
Tank #1 \\ gal Tank #2		gal Pretreatmen	t tankga	al Pump Tank	gal
5. Other information:	List any troubleshooting,	minor repairs co	nducted, tank safe	ty concerns, or oth	er concerns.