

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a va	id maintenance p	ermit. This permit r	nust be completed	
prior to performing maintenance activi	ties and remain on	site for the durat	ion of the maintenar	nce activity.	
Date of Maintenance: 12-9-16 Reason			ja		
Property Address: 9937 Otchipa	Je AVEN F	roperty Owner's N	lame: Seve	Missler	
Municipality: Stillway 71P: 55	2 Property Idea	ntification Number	:		
Maintenance Permit No:	Maintainer Name ar	d License No	2989 Sch	lomka ser	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped	Liquid Level of Tank in				
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements) = % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Mainten Were all covers securely replaced? Yes Is there evidence of tank leakage from a see evidence of damaged, cracked, or structure 	□ No eptic, holding, preti	eatment or pump	tank below the ope		
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes 🗹 No	☐ Yes ⋈No	☐ Yes ☒Ño		
Septic/Holding Tank #2	☐ Yes No	☐ Yes ☒No	☐ Yes ☒No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remove	d?				
Tank #1 00 gal Tank #2 600	gal Pretreatmen	t tank	gal Pump Tank	gal	
5. Other information: List any troubleshootin	g, minor repairs co	nducted, tank saf	ety concerns, or oth	er concerns.	