

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a vali	d maintenance per	mit. This permit must be o	complete
prior to perfor	ming maintenance activitie	es and remain op-	site for the duratio	n of the maintenance activ	ity.
Date of Maintenance:	5-5-17Reason f	or Maintenance: _	Keal	laint	
1 5	019 77044	M 11	Our orda Na	me. Philiptkinhard	Fara
Property Address: 1	1961 000-	DI /U PI	roperty Owner's Na	me: 7 1/1/10 /K compeny	1 Cular
Municipality: Sca	rdia ZIP:	Property Iden	tification Number:		
Maintenance Permit No	D: <u>V5803;612Z</u> M	aintainer Name and	d License No. Smili	e's Sewer Service/L2428	
Maintenar	nce Performed	Tank Measu	urement (must be d	completed if tanks NOT pur	nped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers see3. Is there evidence of	nove septage: Maintenan curely replaced? Yes C of tank leakage from a sept ged, cracked, or structura	\square No	eatment or pump t	ank below the operating de	epth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐NO	☐ Yes ☑ No	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes ☐No	☐ Yes ☐No	☐ Yes ☐No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐No	☐ Yes ☑No	☐ Yes ☐ No	
Tank #1/200	of septage were removed? gal Tank #2/250 : List any troubleshooting,	gal Pretreatment	tankganducted, tank safe	l Pump Tank <u>///</u> ga ty concerns, or other conce	
			/		
				1 11	