

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must be | completed in its entirety to | o constitute a val | d maintenance per | mit. This permit mu | ust be completed |
|---|------------------------------|--|------------------------|----------------------|------------------|
| <u>prior</u> to perfor | ming maintenance activitie | es and remain on- | site for the duratio | n of the maintenance | e activity. |
| Date of Maintenance: | 5 - 1 - 17 Reason for | or Maintenance: | Rea M. | ach 1 | |
| 7 | 160 Dad | , – | roperty Owner's Nai | ma Chika 'e | |
| Property Address: | 200000 | 101 | operty Owner's Nai | ile. Cirky | |
| Municipality: | Mid ZIP | Property Iden | tification Number: _ | | |
| Maintenance Permit No | : <u>e269896143</u> Ma | aintainer Name an | d License No. Smili | e's Sewer Service/L2 | 428 |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | | Liquid Level of Tank in | | | |
| ☐ Sludge and scum measured | | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | | Sludge + Scum / Liquid Level X 100 | | | |
| ☐ Yes ☐ No (if no provide measurements) | | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 1. Access used to rem | nove septage: Maintenan | ce Hole \Box Other (e | nter authorization cod | de) | |
| 2. Were all covers securely replaced? Yes No | | | | | |
| 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | |
| | Septic/Holding Tank #1 | ☐ Yes No | ☐ Yes ☐No | ☐ Yes ☐No | |
| | Septic/Holding Tank #2 | ☐ Yes ☑No | ☐ Yes ☐ No | ☐ Yes ☐No | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| 4. How many gallons | of septage were removed? | | | | |
| Tank #1 /500 gal Tank #2 /500 gal Pretreatment tank gal Pump Tank | | | | | gal |
| 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns. | | | | | |
| | | | | | |
| | Ma | (-00) | | | |
| 6. Location of septage disposal: | | | | | |