

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety t	o constitute a val	id maintenance pe	rmit. This permit m	ust be complete
<u>prior</u> to perform	ning maintenance activitie	es and remain on-	site for the duration	on of the maintenanc	ce activity.
Date of Maintenance:	(-27-17 Reason f	or Maintenance: _	Kea Mail	1	
Property Address:	1520 Oakh.41	- 1 41		me: Michelle	McCarty
Municipality: 500	21P.55/	73 Property Ider	tification Number:		
	0-17/ (111)	_		ie's Sewer Service/L2	
Maintenance Permit No	:97//6w6191 M	anitamer Name an	d Elcense No	ic 3 Sewer Service / LZ	120
/ Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers sec Is there evidence o 	ove septage: Maintenan urely replaced? Yes I f tank leakage from a sept ged, cracked, or structura	□ No tic, holding, pretr	eatment or pump	tank below the opera	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
•	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑No	☐ Yes ♠No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐No	☐ Yes ☑No	☐ Yes 🖾 No	
Tank #1 1200	of septage were removed gal Tank #2 List any troubleshooting,	gal Pretreatmen		al Pump Tank <u>SC</u> ety concerns, or othe	gal er concerns.
6. Location of septage	1			1.0/	