

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
prior to perform	ning maintenance activiti	es and remain on-	site for the duratio	n of the maintenan	ce activity.	
Date of Maintenance: 5-1-17 Reason for Maintenance: Cleaning						
Property Address: 14	277 St Croix	Tr P	roperty Owner's Na	me: Patrick	Shields	
Municipality: <\fi//~	vater ZIP: 5500	Property Iden	tification Number:			
Municipality: Stillwater ZIP: 55080 Property Identification Number:						
Maintenance Permit No	1554/ <b>66</b> 138 M	anitamer Name an	d License No. Sinici	e 3 Sewer Service, Ez	. 120	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
		Sludge + Scum / Liquid Level X 100				
Yes 🗆 No (if r	no provide measurements)	= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Access used to remove septage:  Maintenance Hole Other (enter authorization code)</li> <li>Were all covers securely replaced? Yes No</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?</li> </ol>						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ੴNo		
	Septic/Holding Tank #2	☐ Yes ☐Ńo	☐ Yes ☐No	☐ Yes ☐ No		
	Pretreatment Tank	$\square$ Yes $\square$ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ੴNo		
4. How many gallons	of septage were removed	?				
Tank #1 1250 gal Tank #2 1250 gal Pretreatment tank gal Pump Tank 300 gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
	nla					
6. Location of septage	e disposal:					