

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permi

		directs de semanties.				
I prior to r	est be completed in its en	activities and rema	e a valid maintena	nce permit. This per	mit must be comp	
	performing maintenance		Λ	duration of the main	tenance activity.	
Date of Maintena	-	eason for Maintenar	nce: DM			
Property Address:	: 7341 190th	. St MPY	Property Owne	r's Name: +000 c	ilun	
Municipality:	ZIP:		Identification Num	AV. C IV. S. G. C.		
Maintenance Perm	it No: 18254g64	C	e and License No. (		2110	
Cold Cold		100				
☐ Tank(s) Pumped		Liquid Level	Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need		Sludge + Scun	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (	(if no provide measuremen	its) = % Sludge & :	Scum	Tanks must be pumpe	d if 25% or greater	
1 Across used to n	America company William				o, Broate,	
	emove septage: Mainto		(enter authorization	code)	·	
	securely replaced? Ye					
evidence of dan	of tank leakage from a snaged, cracked, or struct	eptic, holding, pre urally unsound mai	treatment or pum <sub>i</sub> ntenance hole cov	p tank below the operers?	erating depth or	
*	Tank	Leaking Out	Leaking In	Cover Damage		
	Tank Septic/Holding Tank #1	Leaking Out  Yes ANo	Leaking In  Yes No	Cover Damage  ☐ Yes ☑No		
×			Description description of the second			
*	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☑No	☐ Yes ੴNo	☐ Yes ☑No		
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☑No ☐ Yes ☑No	☐ Yes ☐No ☐ Yes ☐No	☐ Yes ♠No☐ Yes ♠No		
How many gallons of	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☐No ☐ Yes ☐No ☐ Yes ☐No	☐ Yes ☐No	☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☑No		
Tank #1 _ 100 to	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ Pretreatment	☐ Yes ☐ No	☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☐ No ☐ Yes ☐ No	gal	
Tank #1 _ 100 to	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ Pretreatment	☐ Yes ☐ No	☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☐ No ☐ Yes ☐ No	gal	
Tank #1 _ 100 to	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ Pretreatment	☐ Yes ☐ No	☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☑No ☐ Yes ☐ No ☐ Yes ☐ No	gal concerns.	