07-032-19-21-0002

Rep	orting Information	A		
Date	of maintenance: 24May1	7 / Reason for	maintenance: SSTS Co	ompliance
Prop	erty address: 23209 St Croix	Tr N (32-031-19-33-0007-1) . Ci	ty: Scandia	State: MN Zip: 55073
Prop	erty owner's name: National	Park Service - St. Croix NSR (attn:	Larry Bloomer)	
Prop	erty-owner's address if different	401 North Hamilton Street		
City:	St. Croix Falls	State: WI Zip: 54024	Phone: (715)755-2430	Fax: (715)755-2578
1.	Access used to remove sept	age: 🛛 Maintenance hole 🔲 C	Other (Go to #3 below)	
2.	If maintenance hole was used, were all covers securely replaced?			
	Explanation:			
3.	If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement.			
	I,, refuse to allow the removal of the solids and liquids through the maintenance			
	(Owner's name)			
	hole, I understand that removal of solids and liquids through other access points is not considered maintenance.			
	Owner's signature:		Da	te:
4.	Is the tank designed as a leaky tank? (Example: seepage pit, cesspool, drywell, leaching pit)			
	Tank #1: ☐ Yes ☒ No Verification method used? _visual			
	Tank #2; ☐ Yes 🖾 No	Verification method used? visua	al	
5.	ls there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked or structurally unsound maintenance hole covers?			
	Tank	Leaking out	Leaking in	Cover damage
_	Septic/holding Tank #1	☐ Yes ☒ No	☐ Yes ☒ No	☐ Yes ☒ No
_	Septic/holding Tank #2	☐ Yes No	☐ Yes 🔯 No	☐ Yes ⊠ No
_	Pretreatment Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No
_	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
6.	How many gallons of septage were removed?			
	Fank #1: 1,000 Tank #2: 1,000 Pretreatment Tank: N/A Pump Tank: N/A			
7.	Is there any sensory (smell and/or sight) evidence of non-domestic wastes?			
	☐ Yes ☑ No Please explain:			
	Disposal site: Wastewater treatment plant Land application Other (please explain below)			
	Explanation:			
	List any troubleshooting, minor repairs conducted, tank safety* concerns or other concerns:			
	— 1939			
8.	Certification: I hereby certify as a State of Minnesota-certified SSTS Maintainer that I personally conducted the work and			
J.	made the observations, or directly supervised others in the performance of this job.			
	Maintainer's name and address:Jim/Row Sewer Service, Inc. 412 Bench St/POB 236; Taylors Falls, MN 55084			
	Maintainer's license #: Maintainer's phone:			51)226-8802
	Maintainer's signature: Date: 24May17			
	V	· V		