

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety ming maintenance activit					
					nce activity.	
	2-13-17 Reason					
Property Address: 5	555 Yearts Am	e. No.	Property Owner's	Name: Bill V	ogel	
Municipality:	Elmo ZIP: 55	Property Ide	ntification Numbe	er:		
Maintenance Permit N	0:952656502	Maintainer Name a	nd License No. Pi	nky's Environmental S	ewer Service/L1673	
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements) :		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers see 3. Is there evidence of	nove septage:	□ No otic, holding, preti	reatment or pum	p tank below the ope	rating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 1250	gal Tank #2	gal Pretreatmen	t tank	gal Pump Tank	gal	
5. Other information:	List any troubleshooting	, minor repairs co	nducted, tank saf	fety concerns, or othe	er concerns.	
6. Location of septage	disposal:					