

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

					The same of the sa						
This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed											
<u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.											
Date of Maintenance: 5-13-17 Reason for Maintenance: Reason for Maintenance: Reason for Maintenance:											
Property Address: 2021 Maxwill Ave N Property Owner's Name: Janice Ries was											
Municipality: //ar	ZIP: 550	$\frac{9}{2}$ Property Iden	tification Number:								
Maintenance Permit No	o: <u> J 561 9 w 60 9</u> 9 Ma	aintainer Name an	d License No. <u>Smili</u> e	e's Sewer Service/L	2428						
	\mathcal{U}				2						
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)									
Tank(s) Pumped		Liquid Level of Tank in									
 ☐ Sludge and scum measured Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements) 		Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater									
						1. Access used to rem	nove septage: Maintenand	ce Hole 🗌 Other (e	nter authorization co	de)	
						2. Were all covers securely replaced? 🗹 Yes 🗆 No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or											
evidence of damaged, cracked, or structurally unsound maintenance hole covers? \Box Yes \Box No											
	Tank	Leaking Out	Leaking In	Cover Damage	-						
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes 🗗 No	_						
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No							
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No							
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	_						
4. Harris manus mallama	of contago were removed?	•									
4. How many gallons of septage were removed? Tank #1 5 gal Tank #2 gal Pretreatment tank gal Pump Tank gal											
,	: List any troubleshooting,										
	1 0 /		100	Hall							
6. Location of septage disposal: has he had had the ha											
Smilie's Sewer Service											
22002 Parriers Ave M											

23893 Pomroy Ave N Scandia MN 55073 651-433-3934