Washington ≈ County

SSTS MAINTENANCE REPORT

System Location

Address 6760 CrockusBonny TL		Telephone Number
City Woodbury	State M ZIP	Property ID No./GEO Code
Owner Mark Manowald	Pumping Date 5-10-17	

Contractor

Maintainer Boss Pumping	MPCA License No. 1945	Telephone Number (651) 466-0800

What was done to the system?

- ☒ Tank(s) Pumped
- ☐ Sludge and scum measured.
  Do tanks need to be pumped?
  - ☐ Yes ☐ No (If no provide measurements below)

Report Liquid Capacity in Gallons

Tank 1: 1200 ☒ Pumped   Tank 2: 1200 ☒ Pumped

Tank 3: _____ ☐ Pumped   Tank 4: _____ ☐ Pumped

Total Gallons Pumped: 2400

Visual Inspection (note any problems with the system):

NOTE: This does not serve as a compliance inspection.

*Tank Measurements-Use Only If Tank(s) Were NOT Pumped

Tank Length ____ in. X Tank Width ____ in. X Tank Depth ____ in. = Tank Volume (cubic inches) ____

Tank Radius ____ in. X Tank Radius ____ in. X 3.14 = Tank Volume (cubic inches) ____

Tank Volume (cu. in.) ____ / 231.01 = Liquid Capacity ____ Gallons/ Tank Depth ____ in. = Gallons/Inch ____

Sludge Level ____ in. X Gallons Per Inch ____ = Sludge Volume ____ Gallons

Scum Level ____ in. X Gallons Per Inch ____ = Scum Volume ____ Gallons

Sludge Volume ____ + Scum Volume ____ = Total Sludge and Scum Volume ____ Gallons

Total Sludge and Scum Volume ____ / Liquid Capacity ____ = Percent Sludge and Scum in Tank ____ %

Scum Layer

Effluent

Sludge Layer

Tank Depth measured from invert of outlet pipe to bottom of tank

*Tanks must be pumped if either of the following conditions exist:
1. The top of the sludge layer is less than 12 inches from the bottom of the outlet baffle; or
2. Total sludge and scum volume is greater than 25 percent of the tank's liquid capacity.

Signature _____ Date 5-10-17