

OSTP Soil Observation Log

Project ID:



Client/ Address:	2770 Trading Post Trail S	Legal Description/ GPS:	16.028.20.42.0003
------------------	---------------------------	-------------------------	-------------------

Soil parent material(s): (Check all that apply) Outwash Lacustrine Loess Till Alluvium Bedrock Organic Matter

Landscape Position: (check one) Summit Shoulder Back/Side Slope Foot Slope Toe Slope Slope shape: LL

Vegetation	Lawn	Soil survey map units	472B-Channahon Silt Loam, 1-6%	Slope%	2.0	Elevation:	960
------------	------	-----------------------	--------------------------------	--------	-----	------------	-----

Weather Conditions/Time of Day: PM/Sunny Date: 08/01/17

Observation #/Location: County Verification Observation Observation Type: Auger Probe Pit

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Structure		
							Shape	Grade	Consistence
0-14"	Fine Sand		10YR3/2				Granular	Weak	Loose
14-18"	Fine Sandy Loam		10YR3/4				Granular	Weak	Loose
18"	Bedrock						Massive		

Comments: 44°54'38.0241" 92°48'38.3024" Obstruction at 18". Was pulling up limestone chunks

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

Chris LeClair		C6836	8/1/2017
(County Inspector)	(Signature)	(License #)	(Date)