## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintena	nce 5-15-17 Reason 1	for Maintenance: 3	xeor	Pulling	
Property Address:	22960 Mela				near or the U
Municipality: State WZip Code SSO 23 GEO Code/Property I.D. #:					
What wa	s done to the system?	Tank Meas	surements (must be com	pleted if tanks NOT pumped)	
Tank(s) Pumped		Liquid Level of Tank	Liquid Level of Tank in Sludge Level in Scum Level in.		
Sludge and scum measured.		Elquid Ecver or Turn	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	*	
Do tanks need to be pumped?  Yes No (If no provide measurements)		Total (Sludge + Scu	Total (Sludge + Scum = % Sludge & Scum		
1. Access used to remove septage: Maintenance Hole Other (Go to #3 below)  * Tank must be pumped if this value is greater than 25%.					
2. If maintenance hole was used, were all covers securely replaced? Yes No please explain					
	note was asca, were an earer	<i>y</i>	in promoting in		
Explanation:				· · · · · · · · · · · · · · · · · · ·	
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:					
Ι,	(0	wner's name), refuse to a	allow the removal of solid	s and liquids through the main	tenance
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit					
Tank#1 Yes Yes Verificatio Method Used:					
Tank#2 Yes No Verificatio Method Used:					
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of					
damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
	Pump Tank	Yes Mo	Yes No	Yes No	
6. How many gallons of septage were removed?					
Tank #1 1500 Tank #2 Pretreatment Tank Pump Tank 1,000					
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
-				II d d. d. b. o o wle	
8. Certification:	I hereby certify as a State of and made the observations,	or directly supervised ot	hers in the performance o	of this job.	
Maintainer's N	ame: Hassle Free Septic	Maintain	er's Address: P.O. Box 702	North Branch, MN 55056	
Maintainer's License #: L3287 Maintainer's Phone #: 763-222-4397					
Maintainer's Signature $\frac{2000}{1000}$ Date: $\frac{5-15-1}{1000}$					