3-23



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a val	id maintenance pe	ermit. This permit m	oust be completed	
<u>prior</u> to perfo	rming maintenance activit	ies and remain on-	site for the durati	on of the maintenan	ce activity.	
Date of Maintenance:	<u>4.24-1</u> Reason	for Maintenance:	Routine			
Property Address:	820 Perkins p	he no. b	roperty Owner's Na	ame: Willie F	Zuncy	
Municipality: <u>Stilll</u>	NUTEV ZIP: 550	82 Property Ider	tification Number:		_	
Maintenance Permit N	10: n6432 m6104 1	Maintainer Name an	d License No. Pinky	y's Environmental Sev	ver Service/ L1673	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of T	Liquid Level of Tank ——— in			
\square Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage: Maintena	nce Hole Other (e	nter authorization co	ode)		
2. Were all covers se	ecurely replaced? Yes	□No 2 and	in Landser	ping		
3. Is there evidence	of tank leakage from a sep aged, cracked, or structur	otic, holding, pretr	eatment or pump	tank below the oper	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 / 500	gal Tank #2	_gal Pretreatment	tankga	al Pump Tank	gal	
5. Other information	n: List any troubleshooting	, minor repairs cor	ducted, tank safe	ty concerns, or othe	r concerns.	
		+00				
6. Location of septag	e disposal:	コルル				
	Pinkv	's Environmental Se	wer Service Inc			

PO Box 354
Afton MN 55001
P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.