

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

NT (

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	y to constitute a va	lid maintenance p	permit. This permit i	must be completed
<u>prior</u> to performing maintenance activ	ities and remain on	-site for the dura	tion of the maintena	nce activity.
Date of Maintenance: <u>02-25-17</u> Reaso	n for Maintenance:	Maint	enance	
Property Address: 8618 Tranwood;				Zeichow
Municipality: Use Elmo ZIP: 550	42 Property Ide	ntification Numbe	r:	
Maintenance Permit No: <u>C3245m5625</u>	Maintainer Name a	nd License No.	2989	
Maintenance Regionmed	Tank Meas	surement (must b	e completed if tanks	NOTER (Imped).
☑ Tank(s) Pumped	Liquid Level of	Tank in		
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements	= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers securely replaced? Yes3. Is there evidence of tank leakage from a see evidence of damaged, cracked, or structure.	eptic, holding, preti			rating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ØNo	☐ Yes 风No	☐ Yes ☑No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
, and and training training				
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
,	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No			
Pretreatment Tank Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	gal
Pretreatment Tank Pump Tank 4. How many gallons of septage were remove	☐ Yes ☐ No d? gal Pretreatmen	☐ Yes ☐ No	☐ Yes ☐ No	