

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entiret	y to constitute a va	ilid maintenance p	ermit. This permit	must be completed	
<u>prior</u> to perfo	rming maintenance activ	ities and remain or	n-site for the durat	tion of the mainten	ance activity.	
Date of Maintenance:	3-1-2017 Reaso	n for Maintenance:	Mainte	rance		
Property Address:	648 28th St N.	· 	Property Owner's እ	lame: <u>bayle</u>	Harrington	
Municipality: <u>Cake</u> (	Elmo zip:550	42 Property Ide	ntification Number	:	. <b>.</b>	
	10: <u>e5497,5626</u>					
(Alajinena	nce Performed	Tank Mea	surement (must be	completed intank	iNOT pumped)	
⊠, Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
$\square$ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to	be pumped?	Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements	) = % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	curely replaced? 🎾 Yes of tank leakage from a se aged, cracked, or structu	ptic, holding, preti	reatment or pump tenance hole cove	tank below the opers?	erating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	•	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	<b>!?</b>				
Tank #1 1750 gal Tank #2 g		_ gal Pretreatment	tankg	al Pump Tank	gal	
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank safe	ty concerns, or oth	er concerns.	

Maintenance activities must be reported to the Department within 90 days.