

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730



Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance	permit. This permit i	nust be completed
<u>prior</u> to perfo	rming maintenance activit	ies and remain or	-site for the dur	ation of the maintena	nce activity.
Date of Maintenance:	5 10 17 Reason	for Maintenance:	Rowline		
Property Address:	4731 Will Ca	nyenur	Property Owner's	Name: Robert (-wkonie
Municipality: <u></u> い	chang zip: 550	Property Ide	ntification Numb	er:	· ·
Maintenance Permit N	10: <u>13791EG150</u>	Maintainer Name a	nd License No	298°) Schlo	nka serv
a Walnen	lice Performed) Tank Mea	surement (must	e completed)(fitanks	NOTE pumped) 🐒 🤻
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to	Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers se Is there evidence 	move septage: Amaintena curely replaced? Yes of tank leakage from a sep aged, cracked, or structur	□ No otic, holding, pret	reatment or pum	p tank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	·
	Septic/Holding Tank #1	☐ Yes ⊠No	☐ Yes ဩNo	☐ Yes 丞No	
	Septic/Holding Tank #2	□ Yes 🖾 🗖 o	☐ Yes ☐ No	☐ Yes ☑No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 <u>√≎≎</u>	gal Tank #2 <u>\()つ()</u>	gal Pretreatment tank		gal Pump Tank	gal gal
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank sa	fety concerns, or othe	er concerns.