DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 629-/7 Reason for	Maintenance:			_
Property Address: 16750 Pell wo	ed RDN Prope	rty Owner's Name:	ichael Pressen	
Municipality: Grant S	tate Zip Code	551/5 GEO C	ode/Property I.D. #: 15953p695	16
What was done to the system?	Tank Measurements (must be completed if tanks NOT pumped)		mpleted if tanks NOT pumped)	
Tank(s) Pumped Sludge and scum measured. Do tanks need to be pumped?	Liquid Level of Tan Total (Sludge + Scu			*
Yes No (If no provide measurements)				
1. Access used to remove septage: Maintenar	nce Hole	Go to #3 below)	 Tank must be pumped if this value is greater than 25%. 	ā
2. If maintenance hole was used, were all covers se	ecurely replaced? 🏿 🏋	Yes No please exp		
Explanation:				
3. If owner refuses to allow a Subsurface Sewag them complete and sign the following statem	e Treatment System	(SSTS) to be pumped	through the maintenance hole, have	•
			T	
(owner's name), refuse to allow the removal of solids and liquids through the maintenance hole. I understand that removal of solids and liquids through other access points is not considered maintenance.				
			dered maintenance.	
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit				
Tank#1 Yes No Verificatio Method Us	ed:			_
Tank#2 Yes No Verificatio Method Us	ed:			
5. Is there evidence of tank leakage from a septi damaged, cracked, or structurally unsound m	c, holding, pretreat aintenance hole cov	ment or pump tank bel ers?	ow the operating depth or evidence o	of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ∠ No	☐ Yes ☐ No	☐ Yes No No	
Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
6. How many gallons of septage were removed?				
Tank #1 / Tank #2 / OTT Pretreatment Tank Pump Tank				
7. Other information: List any troubleshooting, i			erns, or other concerns.	
8. Certification: I hereby certify as a State of Minn and made the observations, or di				-
Maintainer's Name: Olsons sewe	Maintainer	's Address: 7138	your STN Facilla	42
Maintainer's Name: Olsons sewe Maintainer's License #: Maintainer Maintainer's Signature	's Phone #: 65/-4	64-2082		
Maintainer's Signature		Date: 4	29-17	