## Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

prior to perfor	completed in its entirety ming maintenance activi	ties and remain on-	site for the duration	rmit. This permit mon of the maintenan	nust be completed ace activity.	
Date of Maintenance:	Ing 1,	n for Maintenance: _		$\omega$	7	
Property Address: 2	740 Justen		roperty Owner's Na	me: <u>larren</u>	/ auam	
Municipality 7 ha	1 zip:551	Property Iden	tification Number:			
Maintenance Permit N	o: VZ199+6761	Maintainer Name an	d License No. <u>Smili</u>	e's Sewer Service/L2	428	
	/			•		
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum n	neasured	II •		Scum Level in Tank		
Do tanks need to			Sludge + Scum / Liquid Level X 100   = % Sludge & Scum Tanks must be pumped if 25% or greater			
$\square$ Yes $\square$ No (if	no provide measurements	i)    - % studge & see				
3. Is there evidence	curely replaced? Yes of tank leakage from a seaged, cracked, or structu	eptic, holding, pretr	eatment or pump tenance hole cove	tank below the oper	rating depth or	
•	Tank	Leaking Out	Leaking In	Cover Damage		
	Tank Septic/Holding Tank #1	Leaking Out	Leaking In  Yes A	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑Mo	☐ Yes ☑No	☐ Yes ☑No		
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☐No		
Tank #1 1000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank  of septage were remove gal Tank #2 List any troubleshooting	☐ Yes ☐ No ☐ Yes ☐ Ro	☐ Yes ☐No	☐ Yes ☐ No		

Smilie's Sewer Service 23893 Pomroy Ave N Scandia MN 55073 651-433-3934