

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

<u>טו וטו</u> גט א כ ו וט	rming maintenance activi				must be completed	
	6-6-17 Reason		1 / 1	on or the maniten	ance activity.	
	1045 237 th st			Danin	Could	
Municipality:	ZIP: 530	73 Property Ider	tification Number:			
Maintenance Permit N	40: <u>c6616i6793</u>	Maintainer Name an	d License No. <u>Smili</u>	e's Sewer Service/	L2428	
				<u>.</u>		
Maintenance Performed			Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		II ·	ankin	Scum Level in Tan	k in	
Sludge and scum measured		11 -	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to	• •	= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (If	no provide measurements	<u> </u>				
1. Access used to re	move septage: 🗹 Maintena	ance Hole \Box Other (e	nter authorization co	de)		
2. Were all covers se	ecurely replaced? 🏿 Yes	□No				
	of tank leakage from a se		eatment or pump	tank below the op	erating depth or	
evidence of dam	aged, cracked, or structu	rally unsound main	tenance hole cove	rs? 🗌 Yes 🏿 No		
	Tank	Leaking Out	Leaking In	Cover Damage	_	
	Septic/Holding Tank #1		☐ Yes 🌠 No		_	
	-	•	**	☐ Yes 🄀 No		
	Septic/Holding Tank #2	🗌 Yes 💢 No	Yes X No			
				☐ Yes 🗖 No		
	Pretreatment Tank	·	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank Pump Tank	☐ Yes ☐ No			₩	
4. Have many gallon	Pump Tank	☐ Yes ☐ No☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	₩ . #	
4. How many gallons	Pump Tank of sentage were remove	☐ Yes ☐ No☐ Yes ☑ No☐ Yes ☑ Yes ☑ Yes ☑ Yes ☑ Yes ☑ Yes ☐ Y	□ Yes □No □ Yes 🌠 No	☐ Yes ☐ No ☐ Yes 🌠 No	<i>-∮</i>	
Tank #1 1000	Pump Tank s of septage were removedgal Tank #2	☐ Yes ☐ No ☐ Yes ②No ☐ Yes ②No d? ☐ gal Pretreatment	☐ Yes ☐ No ☐ Yes 🌠 No ☐ tankg	☐ Yes ☐ No☐ Yes ☒No☐ Yes ☒No☐ Yes ☒No☐ Yes ☒	−≠ gal her concerns.	
Tank #1 1000	Pump Tank of sentage were remove	☐ Yes ☐ No ☐ Yes ②No ☐ Yes ②No d? ☐ gal Pretreatment	☐ Yes ☐ No ☐ Yes 🌠 No ☐ tankg	☐ Yes ☐ No☐ Yes ☒No☐ Yes ☒No☐ Yes ☒No☐ Yes ☒	− gal her concerns.	
Tank #1 1000	Pump Tank s of septage were removed gal Tank #2 1000 n: List any troubleshooting	Yes No Yes No d? gal Pretreatment	☐ Yes ☐ No ☐ Yes 🍎 No ☐ tankganducted, tank safe	☐ Yes ☐ No☐ Yes ☒No☐ Yes ☒No☐ Yes ☒No☐ Yes ☒	eoggal her concerns.	
Tank #1 1000	Pump Tank s of septage were removed gal Tank #2 1000 n: List any troubleshooting	Yes No Yes No d? gal Pretreatment	☐ Yes ☐ No ☐ Yes 🍎 No ☐ tankganducted, tank safe	☐ Yes ☐ No☐ Yes ☒No☐ Yes ☒No☐ Yes ☒No☐ Yes ☒	gal gal	

Smilie's Sewer Service 23893 Pomroy Ave N Scandia MN 55073 651-433-3934

Maintenance activities must be reported to the Department within 90 days.