

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety					
<u>prior</u> to perfor	ming maintenance activit		1/0 1/1	. ———	ce activity.	
Date of Maintenance:	Reason	for Maintenance: _	, , , , , , , , , , , , , , , , , , , 	a()	· 1 () 1	
Property Address:	440 55rd =	<u>>∕/</u>	roperty Owner's Na	ame: Charlest C	athy Gierk	
Municipality: <u>La Ke</u>	El 010 ZIP:556	<u> 24</u> Z Property Ider	tification Number:			
Maintenance Permit No	: NO337a 6654	Maintainer Name an	d License No. Smili	le's Sewer Service/L2	428	
•						
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
▼ Tank(s) Pumped			Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in			
Sludge and scum m	easured	II = .			in	
Do tanks need to be pumped?		II = -	Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
\square Yes \square No (if no provide measurements))				
1. Access used to rem	ove septage: Maintena	ance Hole 🗌 Other (e	nter authorization co	ode)		
	curely replaced? 12 Yes		÷	,		
	of tank leakage from a se		eatment or pump	tank below the order	ating depth or	
	ged, cracked, or structu				3	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	□ Yes 🕩 No	☐ Yes ☐No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐No	□ Yes 🖾 No	☐ Yes ☐No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	of septage were remove					
, -	_gal Tank #2 <u>750</u>					
5. Other information:	: List any troubleshooting	g, minor repairs co	nducted, tank safe	ety concerns, or other	er concerns.	
					· 	
/ Landing of contage	diamonals /a o O (land	Atolo	_	
6. Location of septage	anshosar The			147		
		Smilie's Sewer	Service	/		

23893 Pomroy Ave N Scandia MN 55073 651-433-3934