## Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety ming maintenance activit					
Date of Maintenance:		for Maintenance: _	_		<u> </u>	
Property Address: 16	781 205th St N	P	Property Owner's Name: John Wilebski			
	rdia zIP: 5507					
	10: C 6325 N 6775 N				— <del>1</del> 28	
		, , , , , , , , , , , , , , , , , , , ,			<u>,                                      </u>	
			<del>.</del>			
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)	
🔀 Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		11	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
Do tanks need to be pumped?		= % Sludge & Sci				
☐ Yes ☐ No (1f	no provide measurements)					
1. Access used to rer	<b>nove septage: </b> Maintena	nce Hole $\Box$ Other (e	nter authorization co	de)		
2. Were all covers se	curely replaced? 🏿 Yes	□No				
	of tank leakage from a sep				ating depth or	
evidence of dame	aged, cracked, or structur	ally unsound main	tenance note cove	rs! ⊔ Yes ⊔ No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🏋 No	☐ Yes 🔼 No	☐ Yes 🕅 No		
	Septic/Holding Tank #2	☐ Yes 🏿 No	☐ Yes 🖾 No	☐ Yes <b>冬</b> No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes 🔼 No	☐ Yes Æ No	☐ Yes ⊠No		
Tank #1 1000	of septage were removed gal Tank #2 <u>1000</u> n: List any troubleshooting	gal Pretreatmen g, minor repairs co	nducted, tank safe			
6. Location of septag	e disposal: Lav	nd Appi	ird			
		Smilie's Sewer	Service			

23893 Pomroy Ave N Scandia MN 55073 651-433-3934