

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety prior to performing maintenance activi	ties and remain on	-site for the durat	ion of the mainter	-	
Date of Maintenance: $b - 6 - 17$ Reason	for Maintenance:	ROUTHE			
Property Address: 4901 Stone bridge	TrIN	Property Owner's N	ame: <u>Sutt</u>	Sherrick	
Municipality: Still newter zIP:550	82 Property Ide	ntification Number:			
Maintenance Permit No: 57850 q 6643				/L2428	
<del>- 3</del>					
				-	
Maintenance Performed	Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped	11 '	Tank in			
/ □ Sludge and scum measured	111 =	Tankin			
Do tanks need to be pumped?	= % Sludge & Sci	Sludge + Scum / Liquid Level X 100   = % Sludge & Scum Tanks must be pumped if 25% or greater			
$\square$ Yes $\square$ No (if no provide measurements					
1. Access used to remove septage:   Maintena	ance Hole Other (6	enter authorization co	nde)		
<ol> <li>Were all covers securely replaced?          Yes     </li> <li>Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure.</li> </ol> Tank	ptic, holding, preti		· · · · · · · · · · · · · · · · · · ·		
Septic/Holding Tank #1		☐ Yes ☑ No	☐ Yes ☑ No	_	
· · · · · · · · · · · · · · · · · · ·	□ Yes 🗚 No	□ Yes ഥ⁄2NO			
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	_	
4. How many gallons of septage were removed Tank #1 1000 gal Tank #2	gal Pretreatmen				
	<del></del>				
1	An to				
6. Location of septage disposal:	M Applia	<b>⊘</b> I			

Smilie's Sewer Service 23893 Pomroy Ave N Scandia MN 55073 651-433-3934