

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## **Subsurface Sewage Treatment System Maintenance Permit**

	completed in its entirety					
<del></del>	ming maintenance activit		site for the durati	on of the maintenance	ce activity.	
Date of Maintenance:	Reason	for Maintenance: _	Neg 1	PILT	1 - 4	
Property Address: 4	C701 I VIVOS ALVE		roperty Owner's Na	.,	Warowski I	
Municipality:	VITE ZIP: 550	Property Ider	tification Number:		<del></del>	
Maintenance Permit N	o: <u>T50395665</u> Li	Maintainer Name an	d License No. <u>Smili</u>	e's Sewer Service/L24	128	
/ Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Y Tank(s) Pumped			Liquid Level of Tank in			
☐ Sludge and scum measured		II *	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?		= % Sludge & Scum Tanks must be pumped if 25% or greater				
☐ Yes ☐ No (if no provide measurements)						
1. Access used to rer	nove septage: Maintena	ince Hole $\square$ Other (e	nter authorization co	ode)		
	curely replaced? Yes		•			
3. Is there evidence	of tank leakage from a sep	otic, holding, pretr			ating depth or	
evidence of dama	aged, cracked, or structur	ally unsound main	tenance note cove	rs: 🗆 res 🗀 no		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ⊅No	☐ Yes ☐No	☐ Yes ⊅No		
	Septic/Holding Tank #2	☐ Yes ☑No	□ Yes 🗗 No	☐ Yes 🗹 No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes 🕩 No	☐ Yes [] No	☐ Yes 🚺 No		
Tank #1 1500	of septage were removed gal Tank #2 (000) n: List any troubleshooting	gal Pretreatmen	t tankg nducted, tank safe	al Pump Tank	gal gal r concerns.	
<del></del>	<u>.</u>		, A	<i>4</i> /		
6. Location of septag	e disposal: WOLL	1 0	lad	Apply		
		Smilie's Sewer	Service			

23893 Pomroy Ave N Scandia MN 55073 651-433-3934