## 1279

## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its and it					
This section must be completed in its entirety	to constitute a va	alid maintenance p	ermit. This permit m	oust be completed	
<u>prior</u> to performing maintenance activit	ies and remain or	n-site for the durat	ion of the maintenan	ce activity.	
Date of Maintenance: $5 - 1 - 10$ Reason	for Maintenance:	10	utine		
Property Address: 1326 Lake Flores	Ave N	Property Owner's N	lame: Fran P	eterson	
h 1		ntification Number			
Maintenance Permit No: 9067555968				_	
700000	wantamer Name a	ild License No. Pink	y's Environmental Sev	ver Service/ L1673	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank ——— in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage:   Maintena	nce Hole Other (	enter authorization co	ode)		
2. Were all covers securely replaced?  Yes			muholes		
	The second secon				
3. Is there evidence of tank leakage from a sep	tic, notaing, preti	reatment or pump	tank below the opera	iting depth or	
evidence of damaged, cracked, or structure	ally unsound main	tenance note cove	rs!  Yes  No		
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐Ño	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ZNo	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed	?				
Tank #1 / >>> gal Tank #2 />>>>	_gal Pretreatmen	tankg	al Pump Tank	gal	
5. Other information: List any troubleshooting,					
	,				
6. Location of septage disposal:	,21			80.7	
Pinky'	s Environmental Se	ewer Service Inc.			
	PO Box 35				

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673