

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	oe completed in its entiret	y to constitute a v	alid maintenance p	permit. This permit	must be completed	
<u>prior</u> to perf	forming maintenance activ	ities and remain o	n-site for the dura	tion of the maintena	ance activity	
Date of Maintenance	e: <u>5-8-/7</u> Reaso	n for Maintenance:	000	tine		
Property Address:			Property Owner's N	Jame: Ku/+T/	Dm SDO	
Municipality:	illuster ZIP:		entification Number		VI-13-63	
Maintenance Permit	No: W599806392	Maintainer Name a	nd License No. Binl	ovic Environmental C		
		Traine a	nd License No. Fills	y's Environmental Se	ewer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
\square Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or						
1. Access used to re	emove septage: Maintena	ence Hole Wether (- Love of greater	
	ecurely replaced? Yes		enter authorization co	ode)		
evidence of dam	of tank leakage from a se	ptic, holding, pret	reatment or pump	tank below the ope	rating depth or	
or adm	naged, cracked, or structur	ally unsound main	tenance hole cove	rs? □ Yes □ No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1	gal Tank #2	_gal Pretreatment	tankga	l Pump Tank	gal	
5. Other information	: List any troubleshooting			v concerns or othe	er concerns	
Pumped of	hrough pipe was	having drain	issues	- Concerns, or other		
6. Location of septage	e disposal:					
	Pinky'	s Environmental Se	wer Service Inc.			
		PO Box 35	4			

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001