4-20



## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a va	lid maintenance pe	ermit. This permit m	ust be completed	
prior to performing maintenance activit					
Date of Maintenance: 5-9-17 Reason	for Maintenance:	Reutine	* ************************************		
Property Address: 145 Lanuanu Sh	cros fel	Property Owner's Na	ame: Derame	Calbum	
1 10 1		ntification Number:			
Maintenance Permit No: 05317 V 6355 A					
<u> </u>	taireamer Hame a	id License No. Filiky	's chimoninental sew	rer Service/ L1673	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank ———— in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to remove septage: $\Box$ Maintenar	nce Hole Other (	enter authorization co	de)		
2. Were all covers securely replaced?   Yes	□ No				
3. Is there evidence of tank leakage from a sep		eatment or pump t	ank below the opera	ating denth or	
evidence of damaged, cracked, or structura				ing depth of	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?					
Tank #1 750 gal Tank #2 750	gal Pretreatment	tankga	l Pump Tank	gal	
5. Other information: List any troubleshooting,	minor repairs co	nducted, tank safet	y concerns, or other	concerns.	
System too old for manholes					
6. Location of septage disposal:					
Pinky's	s Environmental Se	ewer Service Inc.			

Maintenance activities must be reported to the Department within 90 days.