418



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entirety	to constitute a v	alid maintenance p	permit. This permit	must be completed	
<u>prior</u> to perf	orming maintenance activi	ties and remain o	n-site for the dura	tion of the maintena	nce activity.	
Date of Maintenance	: <u>5-3-17</u> Reason	n for Maintenance:	rov	100	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	odeo starix T			Name: Robbi S	tondna	
Municipality: <u></u>			entification Number		BUTANUMA	
	01622660PA:0N					
	+++++++++++++++++++++++++++++++++++++++	manifed Harrie a	nd License No. Fill	ky s Environmental Se	wer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
\square Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage: Maintena	nce Hole Other (
	ecurely replaced? Yes		one dathorization c	ode, 10 DID T	of mir pole	
	of tank leakage from a sep		coatmont or nume	Annie is also suit		
evidence of dam	aged, cracked, or structur	ally unsound main	tenance hole cove	tank below the oper	ating depth or	
				13:		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1	gal Tank #2 💆	_gal Pretreatment	tankg	al Pump Tank	gal	
Other information	: List any troubleshooting,	minor repairs cor	nducted, tank safe	ty concerns, or other	r concerns	
6. Location of septage	e disposal: 514					
	Pinky'	s Environmental Se	wer Service Inc.			
		PO Box 35	4			

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673