

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance SUF Reason	for Maintenance:	7m		
Property Address: 19099 Femuly	pue Pro	perty Owner's Name:	ike Anderson	
Municipality:	State Zip Co	ode 55025 GEOC	ode/Property I.D. #: <u>\$3972e777</u>	16
What was done to the system?	Tank M	Tank Measurements (must be completed if tanks NOT pumped)		
☐ Pank(s) Pumped ☐ Sludge and scum measured. ☐ Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measuremen	Liquid Level of Total (Sludge + S			in.
1. Access used to remove septage: Mainter		(Co to #3 below)	* Tank must be pumped if this va	lue
			is greater than 25%	
2. If maintenance hole was used, were all covers	securely replaced?	Yes No please exp	lain ,	
Explanation:				
3. If owner refuses to allow a Subsurface Sew them complete and sign the following state	age Treatment Syste ement:	em (SSTS) to be pumped t	hrough the maintenance hole, have	P
I, (ov	vner's name), refuse to	allow the removal of solid	ds and liquids through the maintenan	CO
hole. I understand that removal of solids and				ce
4. Is the tank designed as a leaky tank? example:				
Tank#1 Yes Verificatio Method	Used:			
Tank#2 Yes No Verificatio Method	Used:			_
5. Is there evidence of tank leakage from a set damaged, cracked, or structurally unsound	otic, holding, pretrea	ntment or pump tank belo	ow the operating depth or evidence	of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes Ro	☐ Yes ♠No	☐ Yes (No	
Septic/Holding Tank #2	T Yes KNO	TYes TNo	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	Yes Do	T Yes FONO	☐ Yes ☐ No	
6. How many gallons of septage were removed				
Tank #1 [500 Tank #2 [000		ınk Pui	mp Tank 780	
7. Other information: List any troubleshooting				
		,,	The state of the s	
3. Certification: I hereby certify as a State of Min and made the observations, or o	nesota certified SSTS directly supervised oth	Maintainer that I personall ners in the performance of	y conducted the work this job.	_
Maintainer's Name: Olson's Sewer Ser	Vice Maintaine	er's Address: 17638 L	Your Street WE	
Maintainer's Name: <u>Olson's Sewer Ser</u> Maintainer's License #: <u>216</u> Maintaine	er's Phone #: LSL-	464-2082	+ Lake, M S5025	
Maintainer's Signature		Date:		

+ Man ..