DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730



SSTS MAINTENANCE REPORT

Date of Maintenance 8-4-17 Reason	on for Maintenance: ϱ	couler Maintena	nce		
Property Address: 8686 Jamaca	Ave N. Pro	operty Owner's Name:	Lava Ferris		
Municipality: (-cn}			Code/Property I.D. #: <u>C.6560</u>	r 7519	
What was done to the system?	Tank N	Tank Measurements (must be completed if tanks NOT pumped)			
☐ Tank(s) Pumped ☐ Sludge and scum measured. Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurement)	Liquid Level of T Total (Sludge + 5			in.	
1. Access used to remove septage: Maint	enance Hole	r (Go to #3 helow)	* Tank must be pumped if t	his value	
2. If maintenance hole was used, were all cover			is greater than 25%		
	ers securely replaced?	Yes No please ex	plain	•	
Explanation:					
3. If owner refuses to allow a Subsurface Se them complete and sign the following sta	wage Treatment Systontement:	em (SSTS) to be pumped	through the maintenance hole	, have	
	owner's name), refuse t	o allow the removal of so	ids and liquids through the main	tenance	
4. Is the tank designed as a leaky tank? example			dered maintenance.		
Tank#1		игумен, теаспіну ріс			
Tank#2 Yes No Verificatio Metho	d Used:				
5. Is there evidence of tank leakage from a s damaged, cracked, or structurally unsoun	eptic, holding, pretrea	atment or pump tank be	low the operating depth or evi	dence of	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes XNo	☐ Yes ▼No	☐ Yes K No		
Septic/Holding Tank #2	☐ Yes ☐ No	TYes TNo	TYes TNo		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	TYes TNo		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
6. How many gallons of septage were remov	ed?		1 10 1 110		
Tank #1 1150 Tank #2	Pretreatment Ta	ank Pu	ımp Tank		
7. Other information: List any troubleshooting	ng, minor repairs cond	ucted, tank safety conce	erns, or other concerns.		
9 Contidionations I have be said to Contide					
8. Certification: I hereby certify as a State of M and made the observations, o	innesota certified SSTS r directly supervised oth	Maintainer that I persona ners in the performance o	ly conducted the work f this job.		
Maintainer's Name: <u>Olson's Sewer Se</u> Maintainer's License #: <u>216</u> Maintai	Maintaine	er's Address: 17638	yons Street NE		
Maintainer's License #: 216 Maintai				3	
Maintainer's Signature Name:	Dan (grove Date: 8.	-4-17		