DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 8-9-17 Reason for Maintenance: Regular			
Property Address: 9611 Scandia TrlN Property Owner's Name: Melinda Leise			
Municipality: Forgs Cake State MN Zip Code 550 25 GEO Code/Property I.D. #:			
What was done to the system? Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped			
Sludge and scum measured.	Liquid Level of Tank	in. Sludge L	Level in. Scum Level in.
Do tanks need to be pumped?	Total (Sludge + Scum	n) / Liquid Lev	vel = % Sludge & Scum
Yes No (If no provide measurements)			
1. Access used to remove septage: Maintenance Hole Other (Go to #3 below) * Tank must be pumped if this value is greater than 25%.			
2. If maintenance hole was used, were all covers securely replaced? Yes No please explain			
Explanation:			
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:			
l, (owner's name), refuse to allow the removal of solids and liquids through the maintenance hole. I understand that removal of solids and liquids through other access points is not considered maintenance.			
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit			
Tank#1 Yes No Verificatio Method Used:			
Tank#2 Yes No Verificatio Method Used:			
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?			
Tank Lo	eaking Out	Leaking In	Cover Damage
Septic/Holding Tank #1	Yes No	Yes No	Yes TNo
Septic/Holding Tank #2	Yes No	□ Yes □ No	□ Yes □ No
Pretreatment Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No
Pump Tank	Yes T No	☐ Yes ☐ No	☐ Yes ☐ No
6. How many gallons of septage were removed?			
Tank #1 \700 Tank #2	Pretreatment Tank	Pum	np Tank
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.			
O Cambification I have been side of the same side of the			
8. Certification: I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.			
Maintainer's Name: Olson's Sewer Senire Maintainer's Address: 17638 Lyons Street NE Maintainer's License #: 216 Maintainer's Physics # Lelee, MW 55028			
Maintainer's License #: 216 Maintainer's Phone #: iS1-464-2082			
Maintainer's Signature Date: 8-9-17			