DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

Pd

SSTS MAINTENANCE REPORT

| Date of Maintenance \$17/17 Reason | on for Maintenance: | Majortenence Po | mplm | | | |
|--|---|--|---------------------------------------|---|--|--|
| Property Address: 16909 / deal | AJEN P | roperty Owner's Name: | Tyde + Vonnie Kete | Isan | | |
| Municipality: Mahtomedi | | | Code/Property I.D. #: 99126a | | | |
| What was done to the system? | What was done to the system? Tank Measurement: | | | (must be completed if tanks NOT pumped) | | |
| ☐ Tank(s) Pumped ☐ Sludge and scum measured. Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurem | Liquid Level of Total (Sludge + | | | in. | | |
| 1. Access used to remove septage: Maint | | er (Go to #3 below) | * Tank must be pumped if t | his value | | |
| 2. If maintenance hole was used, were all covered to the covered t | | | is arostor than 250/ | , | | |
| Explanation: fourped there of 3. If owner refuses to allow a Subsurface Se | wage Treatment Syst | em (SSTS) to be pumped | through the maintenance hole | . have | | |
| them complete and sign the following sta | atement: | | | , | | |
| l,(| owner's name), refuse | to allow the removal of so | ids and liquids through the main | tenance | | |
| hole. I understand that removal of solids an | d liquids through othe | r access points is not cons | dered maintenance. | | | |
| 4. Is the tank designed as a leaky tank? example | | , drywell, leaching pit | | | | |
| Tank#1 Yes No Verificatio Metho | d Used: AS B. | (+ | | | | |
| Tank#2 Yes No Verificatio Metho | d Used: | | | | | |
| 5. Is there evidence of tank leakage from a s damaged, cracked, or structurally unsoun | eptic, holding, pretre | eatment or pump tank be | low the operating depth or evi | dence of | | |
| Tank | Leaking Out | Leaking In | Cover Damage | | | |
| Septic/Holding Tank #1 | ☐ Yes ☒ No | ☐ Yes ☒ No | ☐ Yes ☒ No | | | |
| Septic/Holding Tank #2 | ┌ Yes ┌ No | ☐ Yes ☐ No | TYes TNo | | | |
| Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | TYes TNo | | | |
| Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | | |
| 6. How many gallons of septage were remov | ed? | | | | | |
| Tank #1 Tank #2 | Pretreatment Tank Pump Tank | | | | | |
| 7. Other information: List any troubleshooting | g, minor repairs con | ducted, tank safety conc | erns, or other concerns. | | | |
| 8. Certification: I hereby certify as a State of M and made the observations, o | innesota certified SSTS r directly supervised of | Maintainer that I persona hers in the performance o | lly conducted the work f this job. | | | |
| Maintainer's Name Olson's Sewer Se | maintain Maintain | er's Address: 17638 | your Street NE | | | |
| Maintainer's Name: Olson's Sewer Se Maintainer's License #: 216 Maintain | ner's Phone #: LSL | -464-2082 | st Lalee, M SSO2 | 3 | | |
| Maintainer's Signature + Name: | | Date: < | 1/2/12 | | | |